# LOCAL NOTICE TO MARINERS

U.S.Department of Transportation

**United States Coast Guard** 

## **WEEKLY SUPPLEMENT - JUNE 1997**

\*\*FAX-ON-DEMAND - LOCAL NOTICE TO MARINERS AT (703) 313-5931 or 5932 \*\* \*\* Electronic Bulletin Board Service: (703) 313-5910 \*\*

300 to 28.8 bps, 8 data bite, no parity 1 stop bit NIS watchstander, 24 hours a day at (703) 313-5900 ~ INTERNET ADDRESS ~ http://www.navcen uscg.mil OR ftp://ftp.navcen.uscg.mil

Issued by: Commander (mon)

Seventeenth Coast Guard District

P.O. Box 25517 Juneau, AK 99802-5517 Telephone: (907) 463-2262 (0800-1600) (907) 463-2004 (1600-0800)

Facsimile:(907) 463-2273

Questions comments or additional information on this Local Notice to Mariners or the Local Notice to Mariners mailing list (additions, deletions, corrections) should be directed to the address above.

For faster service, get the 17~ District Local Notice to Mariners via e -mail. To get on our electronic mailing list, send us an e -mail at: akcgnav@alaska.net

#### LIGHT LIST REFERENCE: COMDTPUB P16502.6 VOL. VI 1996 EDITION

### BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by Broadcast Notice to Mariners 161/97 through 270/97 and still in effect is included in this notice.

## USE OF THE LOCAL NOTICE TO MARINERS

The Weekly Supplemental editions contain new information available subsequent to the issue of the Monthly edition. To ensure having complete information concerning the waterways of the Seventeenth Coast Guard District, consult Monthly edition 19/97.

## I SPECIAL NOTICES

#### POTATO POINT- DGPS- OFF-AIR

The Potato Point DGPS site is authorized intermittent off-air periods between 1500Z and 0400Z on 08, 09, 24, and 25 July 97.

#### II <u>DISCREPANCIES DISCREPANCIES CORRECTE</u>D

## **DISCREPANCIES:**

LLNR NAM	ME OF AID	STATUS	CHART	BNM	LNM			
22429.5	Thorne Bay Channel Daybeacon "7"	Destroyed	17405	657/96	48/96			
23801 (	Coghlan Island Daybeacon "1"	Partially Destroyed	17315	187/97	21/97			
26100 E	East Amatuli Island Light	Dayboard Destroyed	16640	199/97	23/97			
DISCREP	ANCIES/PRIVATE AIDS:							
LLNR NAM	ME OF AID	STATUS	CHART	BNM	LNM			
27467 AP	L Dolphin Lights	Extinguished	16011	178/97	20/97			
27467 AP	L Shoal Lighted Buoys	Extinguished	16011	178/97	20/97			
DISCREPANCIES CORRECTED								
LLNR NAM	ME OF AID	STATUS	CHART	BNM	LNM			
27810 E	Ekuk Range Front Light	Watching Properly	16591	205/97	23/97			

Date: 24 JUN 1997 NOTICE NUMBE

26/97

26/97

26/97

D . . . .

#### III TEMPORARY CHANGES TEMPORARY CHANGES CORRECTED

#### **TEMPORARY CHANGES:**

LLI	NR NAME OF AID	STATUS	CHART	BININ	LINIVI
110	5 Cape St.Elias Bell Buoy "2"	TUB	16723	121/97	13/97

## REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

#### TEMPORARY CHANGES (Cont)

IEMPO	RARY CHANGES	ont)				
LLNR	NAME OF AID		STATUS	CHART	BNM	LNM
23305.6	Keku Strait Daybea	con "9"	TRUB	17372	188/97	21/97
23305.8	Keku Strait Daybea	con "11"	TRUB	17372	188/97	21/97
26250	Anchor Point Light		FIW 6s 7M	16645	437/96	30/96
25645	Knowles HeadLigte	d Bell Buoy 4	TRLWB		257/97	25/97
IV CHAR	RT CORRECTIONS					
16645		st LNM 25/97 <b>NAD 83</b> Sore Point to Anchor Point		(CCGD1	17)	
	delete:	Lighted Buoy 2		59°26'45.8	"N	151°43'28.9"W
	delete:	Buoy 4		59°26'25.3	"N	151°43'29.5"W
	add:		59°26'45.5	"N	151°43'30.5"W	
		Seldovia Daybeacon 4		59°26'24.7	"N	151°43'33.7"W
16646	10th Ed.6/24/89 La	st LNM 25/97 <b>NAD 83</b>		(BP-156	957)	

AK -Ports of	AK -Ports of Southeastern Cook Inlet				
delete:	Lighted Buoy 2	59°26'45.8"N	151°43'28.9"W		
delete:	Buoy 4	59°26'25.3"N	151°43'29.5"W		
add:	Seldovia Light 2 FI R 4s	59°26'45.5"N	151°43'30.5"W		
	Seldovia Daybeacon 4	59°26'24.7"N	151°43'33.7"W		

16580	9th Ed.5/05/90 Last LNM 07/97 <b>NAD 83</b> AK - Kodiak Island		(CCGD17)	26/97
	add:	Shag Rock Daybeacon 1	57°54'29.0"N	152°47'30.1"W
		Shag Rock Daybeacon 3	57°54'52.6"N	152°48'13.8"W
	change:	Ilkognak Rock Light 1 tollkognak Rock Light Fl W 4s	57°54'49.1"N	152°47'02.2"W

16594		/25/92 Læt LNM 07/97 <b>NAD 83</b> not Bay andKupreanof Strait	(CCGD17)	
	add:	Shag Rock Daybeacon 1	57°54'29.0"N	152°47'30.1"W
		Shag Rock Daybeacon 3	57°54'52.6"N	152°48'13.8"W

Shag Rock Daybeacon 3 57°54'52.6"N 152°48'13.8"W change: Ilkognak Rock Light 1 tollkognak Rock Light FI W 4s 57°54'49.1"N 152°47'02.2"W

## VI PROPOSED CHANGES IN AIDS TO NAVIGATION

1. The Coast Guard is considering removing the bell from Cape St. Elias Bell Buoy "2".

Any interested company or individual wishing to provide comments should contact:

Commanding Officer USCGC SWEETBRIER (WLB 405) P.O Box 300 Cordova, AK 99574 Attn: ENS Bird 907-424-3434

#### VII GENERAL

#### ALASKA- ALASKA PENINSULA WATERWAYS ANALYSIS AND MANAGEMENT SYSTEM (WAMS)

1. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Sitkinak Strait Waterway which includes Sitkalidak Strait, Geese Channel, Alitak Bay and Moser Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty informatic port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects.

2. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Alaska Peninsula Waterway which includes the Semid Islands, Chignik Bay, Sand Point, Korovin Strait, Popof Strait and Unga Strait. The study focuses on the area's aids to navigation system, waterborne commerce marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects.

Any interested company or individual wishing to provide comments or participate in these two user surveys should contact:

Commanding Officer USCGC FIREBUSH (WLB 393) P.O Box 190653 Kodiak, AK 996190653 Attn: WAMS Officer 487-5303

#### VII GENERAL (Cont)

3. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study **K**achemak Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communicatic capabilities, and future development projects. Any interested company or individual wishing to provide comments or participate in this user survey should contact

Commanding Officer USCGC SEDGE (WLB 402) P.O Box 101 Homer, AK 99603 Attn:ENS C. E. Bland (907) 235-5233

## **VIII LIGHT LIST CORRECTIONS**

Note: \* Indicates the column(s) in which a correction has been made or new information added.

(1) LLNR	(2) Name and Location	(3) Position	(4) Characteristics	(5) Height	(6) Range	(7) Structure	(8) Remarks	
		N/W						
21834	Island Point Coast Guard mooring buoy *	54 44.2 130 38.5 *	*	*	*	*	*	26/97
21841	Stone Rock Bay Coast Guar mooring buoy *	d 54 41.7 132 35.0 *	*	*	*	*	*	26/97
21973	Mountain Point Daybeacon 2	2 55 17.6 131 32.5				TR on skeleton towe	r	26/97
22326	REAR RANGE	55 31.6 131 50.6 *	*	*	*	KR on skelton towe	r *	26/97
22327	FRONT RANGE LIGHT	55 32.2 131 49.9	FI W 2.5s	30	7	NR on skelton towe	r	26/97
23545	CORNWALLIS POINT LIGH	T 56 55.9 134 16.4	FI W 4s	34	6	NR on spindle	Obscured from 140° to 345°	26/97
23640	MIDWAY ISLAND LIGHT	57 50.2 133 48.8	FIW 4S	83	7 *	NR on skelton towe	r Obscured from 162° to 210°	26/97
24331	Mcleod Bay Coast Guard mooring buoy	54 41.5 132 41.2 *	*	*	*	*	*	26/97

## IX ADDITIONAL ENCLOSURES

Coast Pilot 9 Change No. 20 Coast Pilot 9 Change No. 21 K. A. Hamblett
Commander, U.S. Coast Guard
Waterways Management and Navigation Safety
Branch
Seventeenth Coast Guard District
By direction of the Commander

Operational Excellence Through Leadership, Teamwork And Continuous Improvement